

- Colorado vehicle since 2017, serviced at Houska Automotive and Markley Motors. Passed Colorado emissions inspections in 2017 and again in 2025.
- Acquired by Pedersen Toyota and offered for sale on July 27, 2026 at 129,285 miles.

PEDERSEN TOYOTA RECONDITIONING

Fourteen separate items, totaling \$6,134.60:

Work Performed	Description	Price
Rear Wheel Bearings	Both rear wheel bearings replaced	\$1,942.50
Differential Mount	Differential mounting bushing and absorber replaced	\$1,077.60
Tires	Four new tires mounted and balanced	\$822.00
Front Brakes	Front brake service	\$588.50
A/C Noise Repair	Passenger seat and trim removed to retrieve a child's toy that had fallen into the air conditioning vent and was causing noise	\$358.00
Oil & Filter Service	Oil and filter change with BG additive service and gasket	\$279.00
Detail	Full interior and exterior reconditioning detail	\$232.25
Used Car Inspection	Full multi-point used-vehicle inspection	\$187.50
Filters	Engine and cabin air filter replacement	\$167.40
Alignment	Four-wheel alignment	\$155.15
Wipers	New windshield wiper blades	\$128.70
Battery Service	Battery tested and serviced	\$98.50
Lighting	Exterior lighting service	\$61.70
Privacy / Data Reset	Previous owner's personal data cleared from vehicle systems	\$35.80
Total Reconditioning Investment		\$6,134.60

The two highlighted items — rear wheel bearings and the differential mount — together account for \$3,020.10 and represent nearly half the total. Both are labor-intensive suspension and drivetrain repairs that a private seller would typically leave for the buyer to discover. CARFAX separately confirms that the brakes were checked and four tires replaced and balanced at Pedersen Toyota on August 14, 2026.

ABOUT THAT AIR CONDITIONING NOISE

During inspection a noise was traced to the air conditioning system. Rather than leaving it, the passenger seat and trim were removed to find the cause: a child's toy had fallen into the vent. It was retrieved and the noise is resolved — no air conditioning components were damaged or needed replacing. It is a small thing, but it is the kind of issue a buyer would otherwise have inherited as a mystery rattle.

SERVICE HISTORY

CARFAX lists 26 service records. Highlights across the vehicle's life:

- Pre-delivery inspection, alignment check and safety inspection at 10 miles (October 2004).
- Serviced consistently at Tony Honda Kona and Tony Honda Hilo in Hawaii from 2004 through 2017, including repeated safety inspections and maintenance inspections.
- Four-wheel alignment performed at 75,658 miles (March 2014).
- Battery and charging system checked, oil and filter changed at 77,901 miles (March 2015).
- Left airbag assembly replaced at 78,633 miles (April 2015) — a service repair, with no airbag deployment ever reported on this vehicle.