



2024 Toyota Tundra Platinum

Vehicle Highlight Sheet



VIN: 5TFWA5DB9RX213789
Mileage: 37,515 miles
Exterior Color: White (Pearl) | Interior Color: Black
Engine: 3.4L Twin-Turbo V6 (i-FORCE) | Drivetrain: 4x4
Location: Pedersen Toyota, Fort Collins, CO

CARFAX SUMMARY

Category	Status
Accidents / Damage	None reported to CARFAX
Structural Damage	None reported to CARFAX
Airbag Deployment	None reported to CARFAX
Total Loss	Never reported to CARFAX
Odometer Rollback	None indicated
Open Recalls	1 open manufacturer recall (NHTSA #25V322) — see disclosure below
Title Brands	Clean — CARFAX Buyback Guarantee: no problem indicated for damage or odometer brands
Ownership	2 previous owners — both personal use, Colorado. Owner 1: 1 year, 9 months (primary). Owner 2: 1 month.
Service Records	11 CARFAX service records on file — predominantly serviced at McDonald Toyota Greeley
Original Manufacturer Warranty	Toyota 3-year/36,000-mile basic warranty (expired on mileage). Original 5-year/60,000-mile powertrain warranty — verify current status with service department.

Source: CARFAX Vehicle History Report pulled 8/10/2026. Report based only on information supplied to CARFAX; not all accidents or issues are reported.

OPEN MANUFACTURER RECALL

One open Toyota safety recall applies to this vehicle. Buyer should verify recall status and completion at any authorized Toyota dealer.

Toyota Safety Recall — NHTSA #25V322 (Recall #25TB06 / 25TA06)

Issued 5/15/2025 by Toyota Motor Sales, USA. Affects 2022–2025 model year Tundra and Tundra HV vehicles, including this VIN.

Concern: Due to moisture accumulation over time, both reverse lamps on the subject vehicles can stop working. If this occurs, the driver's view to the rear can be limited when backing during low ambient light conditions, and there may be no indication to others that the vehicle is operating in reverse. This can increase the risk of a crash.

Remedy: The remedy, when available, will involve replacement of both reverse lamp assemblies with improved assemblies, FREE OF CHARGE. Additionally, the wire harnesses will be repaired for any vehicles identified to have corrosion that has extended into the wire harness connector, FREE OF CHARGE. As of the CARFAX report date, the recall status is listed as "Remedy Not Yet Available" — Toyota estimates the remedy will begin to be available in the 4th quarter of 2025, rolling out in phases. Customers can check status at toyota.com/recall to be notified when the remedy is available.

OWNERSHIP HISTORY

Owner 1 (2024–2026 — primary owner, 1 year 9 months)

Personal use, Colorado. Purchased new August 2024 from McDonald Toyota Greeley (Greeley, CO). Approximately 21,131 miles per year — above the 15,000-mile industry average, reflecting regular use of a full-size pickup. Serviced at McDonald Toyota Greeley for the entire ownership period. Last reported odometer: 37,515 miles.

Owner 2 (2026 — 1 month)

Personal use, Colorado. Brief ownership before the vehicle was offered for sale at Pedersen Toyota. Vehicle serviced at Pedersen Toyota in June and July 2026 for sale preparation.

- Two previous owners — both personal use, both in Colorado.
- Owner 1 was the primary owner and serviced the vehicle exclusively at McDonald Toyota Greeley.
- Vehicle has been in Colorado its entire life — a Colorado vehicle from new.
- Consistent dealership service history with regular oil changes and milestone services.

PEDERSEN TOYOTA RECONDITIONING

Pedersen Toyota's service department completed the following work before offering this vehicle for sale. Pricing reflects the parts and labor invested in each item.

Work Performed	Description	Price
Used Car Inspection	Multi-point used vehicle inspection	\$187.50
Privacy4Cars Data Reset	Cleared previous owner's personal data from infotainment/connected services	\$35.80
Oil & Filter Service	Oil and filter change with BG treatment and drain plug gasket replacement	\$279.00
Wiper Blades	New windshield wiper blades installed	\$100.80
Filters	Engine air filter and cabin air filter replaced	\$226.10
Rotate	Tire rotation	\$125.00
Coolant System Repair	Replaced hose and clamps on coolant system	\$346.40
Broken Bolt Repair	Replaced broken bolt	\$89.50
Full Detail	Complete interior and exterior detail	\$232.25
Total Reconditioning Investment		\$1,622.35

SERVICE HISTORY

CARFAX documents 11 service records. Key entries:

- Pre-delivery inspection completed — 1 mi (July 2024), McDonald Toyota Greeley, Greeley, CO
- Vehicle serviced (accessories installed, maintenance inspection) — 391 mi (September 2024), McDonald Toyota Greeley
- 5,000-mile service, maintenance inspection — 5,511 mi (December 2024), McDonald Toyota Greeley
- 10,000-mile service, cylinder head gasket(s) replaced, oil and filter changed — 10,251 mi (March 2025), McDonald Toyota Greeley
- 15,000-mile service, inspection, maintenance inspection — 15,765 mi (June 2025), McDonald Toyota Greeley
- 20,000-mile service, maintenance inspection, oil and filter changed — 21,394 mi (August 2025), McDonald Toyota Greeley
- Maintenance inspection, tires rotated, vehicle washed/detailed — 26,728 mi (December 2025), McDonald Toyota Greeley
- Maintenance inspection, engine checked — 34,370 mi (April 2026), McDonald Toyota Greeley
- Brakes checked, vehicle washed/detailed — (June 2026), Pedersen Toyota, Fort Collins, CO (sale prep)
- Vehicle serviced — (July 2026), Pedersen Toyota, Fort Collins, CO (sale prep)

Service pattern reflects consistent, on-schedule Toyota dealership maintenance at McDonald Toyota Greeley throughout Owner 1's ownership, with all milestone services (5k, 10k, 15k, 20k) completed on time. Recent sale-preparation service was performed at Pedersen Toyota in June and July 2026.

RELIABILITY & COST TO OWN

- The 2024 Toyota Tundra earned a 5-Star overall safety rating from NHTSA.
- The i-FORCE 3.4L twin-turbo V6 is Toyota's modern full-size truck powertrain, shared across the Tundra lineup. It delivers strong performance (389 hp / 479 lb-ft) with improved efficiency over the previous V8.
- Note: The 2024 Tundra has had a higher-than-average number of NHTSA recalls across the model line. This specific vehicle has 1 open recall (reverse lamps) — see the recall disclosure section above.
- With 37,515 miles and consistent dealership service, this vehicle has been well maintained. Owner 1 drove approximately 21,131 miles per year, which is above average but reflects typical full-size truck usage.
- The 5-year/60,000-mile powertrain warranty status should be confirmed with the service department.

FEATURES WORTH KNOWING

Platinum Trim — Premium Level

- The Platinum is the second-highest trim in the Tundra lineup, featuring premium leather-trimmed seats, wood-grain interior accents, and a 14-inch Toyota Audio Multimedia touchscreen.
- Semi-aniline leather-trimmed seats with heating and ventilation for front seats, heated rear seats, and heated steering wheel.
- Power moonroof and power tonneau cover.
- JBL premium audio system with 12 speakers (verify on this specific build).

Powertrain — i-FORCE Twin-Turbo V6

- 3.4L twin-turbo V6 — 389 horsepower and 479 lb-ft of torque.
- 10-speed automatic transmission with paddle shifters.
- 4x4 with part-time 4WD — well-suited for Colorado weather and towing.
- Maximum towing capacity up to 12,000 lbs when properly equipped.

Comfort & Interior

- CrewMax cab with spacious rear seating.
- Dual-zone automatic climate control with rear vents.
- Power-adjustable front seats with memory.

- Panoramic view monitor with 360-degree camera.
- Wireless Apple CarPlay and Android Auto.
- Qi-compatible wireless charging pad.

Safety — Toyota Safety Sense 2.5

- Pre-Collision System with Pedestrian Detection.
- Full-Speed Range Dynamic Radar Cruise Control.
- Lane Departure Alert with Steering Assist.
- Lane Tracing Assist.
- Automatic High Beams.
- Blind Spot Monitor and Rear Cross-Traffic Alert.
- NHTSA 5-Star overall safety rating.

Towing & Utility

- Maximum towing capacity up to 12,000 lbs (properly equipped).
- Trailer Brake Controller and Tow/Haul mode.
- Multi-terrain Select and Crawl Control for off-road capability.

PERFORMANCE & SPECIFICATIONS

Spec	Value
Engine	3.4L twin-turbo V6 (i-FORCE, DOHC 24-valve)
Horsepower	389 hp
Torque	479 lb-ft
Transmission	10-speed automatic with paddle shifters
Drivetrain	4x4 (part-time 4WD)
Fuel Economy	EPA-estimated 18 city / 23 highway / 20 combined mpg
Seating	5 passengers (CrewMax cab)
Towing Capacity	Up to 12,000 lbs., properly equipped
Bed Length	5.5 ft. (short bed)

SUMMARY

This 2024 Toyota Tundra Platinum is a 2-owner vehicle with 37,515 miles, purchased new in August 2024 from McDonald Toyota Greeley and serviced exclusively there for its first 21 months. The primary owner drove approximately 21,131 miles per year — above the industry average, reflecting regular use of a full-size pickup. CARFAX reports no accidents, no damage, and a clean title. One open manufacturer safety recall applies (NHTSA #25V322 — reverse lamps may become inoperable due to moisture); the remedy is not yet available but will be performed free of charge by Toyota when released. The original 3-year/36,000-mile basic warranty has expired on mileage; the 5-year/60,000-mile powertrain warranty status should be confirmed with the service department. The Tundra earned a 5-Star NHTSA overall safety rating. Pedersen Toyota's service department completed a \$1,622.35 reconditioning process, including a used car inspection, oil and filter service, new wipers and filters, tire rotation, coolant system hose and clamp replacement, broken bolt replacement, and a complete detail.

PEDERSEN TOYOTA — 2024 TOYOTA TUNDRA PLATINUM

Jeff Lee, Internet Sales Manager · (720) 416-6955 · jlee@pedersentoyota.com
Pedersen Toyota · 4455 S College Ave, Fort Collins, CO 80525 · (970) 438-2424
August 10, 2026